

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:13:26	
Image Name	IR_0055.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
seinän ja katon rajasta sekä ikkunan pielestä lämpövuotoa

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:09:11	
Image Name	IR_0058.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
eristelaselementti-ikkunat kylmiä

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:40:15	
Image Name	IR_0059.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
eristelaselementti-ikkunat kylmiä

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:40:24	
Image Name	IR_0060.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
seinän ja katon rajasta sekä ikkunan pielestä lämpövuotoa

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:40:36	
Image Name	IR_0061.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
Kirjastohuone, seinän ja katon rajasta lämpövuotoa

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:40:43	
Image Name	IR_0062.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
Kirjasto huone, seinän ja katon rajasta lämpövuotoa.

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:17:14	
Image Name	IR_0069.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
verstahuone ulkoapäin. ok.

Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:15:37	
Image Name	IR_0064.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
kirjastohuone, patterin pintalämpö



Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:15:55	
Image Name	IR_0065.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
ryhmähuone, patterin pintalämpö

Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:16:12	
Image Name	IR_0066.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
ryhmähuone, patterin pintalämpö

Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:16:42	
Image Name	IR_0067.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

## Description

verstashuone, patterin pintalämpö n. 10 astetta alhaisempi kuin viereisissä huoneissa.

Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:16:47	
Image Name	IR_0068.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

## Description

verstashuone, patterin pintalämpö n. 10 astetta alhaisempi kuin viereisissä huoneissa.

Report Date 11.10.2007

Company  
Address  
Thermographer

Customer  
Site Address  
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:44:03	
Image Name	IR_0046.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

Description
Verstahuone. Lattian rajassa päätyseinällä viileää, pintalämpö sallitun pistemäisen pintalämmön rajalla.

Report Date 11.10.2007

Company

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:10:11 14:43:45	
Image Name	IR_0047.jpg	
Emissivity	0,96	
Reflected Temperature	20,0 °C	
Object Distance	2,0 m	

## Description

Verstahuone. Lattian rajassa päätyseinällä viileää, pintalämpö sallitun pistemäisen pintalämmön rajalla.